

DAMAGE REPORT

Inbound carrier: AS NINA

ASNI348S 348S

06-Dec-2023 14:39

Container	Damage type	Damage location
MNBU0539700	HOLE	TOPROOF
MRKU3655514	DENT	LEFT
MSKU1054250	DENT	RIGHT
MSKU1054250	BENT	LEFT
MSKU7187265	DENT	LEFT
MRKU5505112	BENT	RIGHT
MAEU4694268	CUT	TARPAULIN
TRHU8395884	BULGED	LEFT
TLLU2486027	BULGED	LEFT
EISU9209692	DENT	CORNERPOST
MRKU0470353	BENT	LEFT
MSKU1423189	DENT	LEFT
SUDU7919020	DENT	LEFT
MSKU9312617	DENT	LEFT
MRSU3936535	DENT	CORNERPOST
MSKU5498967	DENT	LEFT
TCNU8809614	TORN	DOORSYSTEM
MRKU6685662	DENT	LEFT
MSKU1635022	DENT	LEFT
MSKU7414733	DENT	LEFT
CAAU2249368	BENT	LEFT
MRSU4557367	IMO LABEL	LEFT
MRSU4557367	IMO LABEL	RIGHT
MRKU3582402	DENT	LEFT
MSKU1065275	DENT	LEFT
SUDU5829246	DENT	LEFT
MRKU9727289	DENT	RIGHT
TRHU8317599	BENT	LEFT




*Signed for receipt only,
without prejudice of liability
Discharged same condition as
loaded.*

*Without any liability accepted
Constanta South Container Terminal
Planning Department*



Container	Damage type	Damage location
MRKU3266493	BENT	RIGHT
MRKU3331027	BENT	RIGHT
MRKU9114435	DENT	RIGHT
GLDU9362059	BENT	LEFT
GLDU9362059	BENT	RIGHT
EGSU9042596	DENT	LEFT
MRKU9039060	DENT	LEFT
TRHU7673039	BENT	LEFT
MRKU7307672	DENT	BOTTOM
SUDU5829056	DENT	DOORSYSTEM
MAEU4082236	CUT	TARPAULIN
MSKU1519594	CUT	LEFT
MRSU3988755	SCRATCHED	RIGHT
TCNU6398237	CUT	TOPROOF
TGHU1807735	TORN	DOORSYSTEM
TGHU1807735	CUT	DOOR
MRKU2031690	DENT	RIGHT
SUDU6759014	DENT	LEFT
MSKU0180973	DENT	RIGHT
MRKU7929341	BENT	BOTTOM
SUDU8951670	DENT	LEFT
MRKU7854880	DENT	RIGHT
TEMU2088167	DENT	RIGHT
TRHU5231470	DENT	CORNER
TLLU8230686	DENT	LEFT
MRKU2258641	DENT	LEFT
MRKU8890080	DIRTY	LEFT
GLDU4003760	DENT	RIGHT
SUDU5322333	DENT	RIGHT
MRKU0290006	DENT	RIGHT
MRKU2541219	DENT	LEFT
MRSU3416847	CUT	LEFT
MAEU4219709	CUT	TARPAULIN
SUDU8664221	TORN	DOORSYSTEM




*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*




Container	Damage type	Damage location
TCLU5040811	HOLE	FRONT
TLLU2284155	DENT	LEFT
SUDU1919887	DENT	CORNERPOST
MSKU5879650	DENT	LEFT
TCKU6639704	BULGED	LEFT
MRKU8916797	DENT	CORNERPOST
SUDU6848997	DENT	RIGHT
MRKU9550207	DENT	RIGHT
MRKU5267729	BENT	LEFT
MRKU5267729	DENT	LEFT
MRSU0063983	BENT	LEFT
HASU1272503	DENT	LEFT
MRKU7812972	BROKEN	CORNER
TRHU4398289	BENT	RIGHT
MRKU4341267	DENT	LEFT
CAAU6400430	DENT	FRONT
MRKU6586588	DENT	LEFT
MRSU4932982	DENT	LEFT
MRKU2295440	DENT	LEFT
MSKU0741760	BENT	RIGHT
MSKU1686689	DENT	BOTTOM
MRKU9925793	DENT	RIGHT
MSKU5508242	BENT	BOTTOM
MRSU4062882	DENT	CORNERPOST
MRSU4062882	DENT	RIGHT
MSKU7636941	DENT	CORNERPOST
MSKU7636941	DENT	CORNER
MRKU3022157	BULGED	LEFT
HASU1274893	DENT	LEFT
MSKU1631074	DENT	LEFT
MSKU0229733	DENT	LEFT
MSKU7261660	DENT	LEFT
MSKU7261660	BENT	LEFT
MRSU4233898	DENT	LEFT



Container	Damage type	Damage location
TRHU1145693	HOLE	LEFT
TCLU3377249	DENT	LEFT
MSKU0213470	DENT	LEFT
HASU4380348	DENT	RIGHT
MSKU3067132	DENT	LEFT
TCKU6728632	DENT	RIGHT
GESU6927258	IMO LABEL	LEFT
MNBU3787300	DENT	TOPROOF
HASU1524879	DENT	RIGHT
MRSU5705453	BENT	LEFT
TRHU5241566	DENT	RIGHT
MRSU5729666	IMO LABEL	RIGHT
MSKU4347246	DENT	RIGHT
MRKU5445862	DENT	CORNERPOST
MRSU3724644	DENT	RIGHT
TRHU4522450	DENT	LEFT
MRKU4130325	BENT	LEFT
MMAU1040023	DENT	CORNERPOST
SUDU6806055	DENT	RIGHT
TCLU2503018	DENT	RIGHT
TCLU2503018	DENT	LEFT
TTNU1262364	TORN	DOORSYSTEM
TTNU1262364	DENT	BOTTOM
MRKU8320386	IMO LABEL	RIGHT
MRKU8320386	IMO LABEL	LEFT
MRKU8320386	IMO LABEL	FRONT
MRKU8320386	IMO LABEL	DOOR
MRKU8320386	HOLE	TOPROOF
MRKU4825528	BROKEN	RIGHT
MSKU5112903	DENT	FRONT
AMFU3100692	DENT	LEFT
SEGU4521840	BENT	RIGHT



 Signed for receipt only,
 without prejudice of liability.
 Discharged same condition as
 loaded.



 Without any liability accepted
 Consentia South Container Terminal
 Planning Department