

DAMAGE REPORT

Inbound carrier: MAX SCHULTE

MASH537S 537S

09-Sep-2025 09:10

Container	Damage type	Damage location
CAIU6802617	DENT	CORNERPOST
MRSU4743090	DENT	FRONT
MRKU7484826	BENT	RIGHT
MRKU7484826	DENT	LEFT
MRKU7484826	DENT	CORNERPOST
MRKU8232834	BENT	RIGHT
MRKU8232834	DENT	LEFT
SUDU1822032	DENT	FRONT
HASU4689297	DENT	FRONT
HAMU3863611	CUT	FRONT
SUDU1937094	DENT	LEFT
UACU5886331	DENT	RIGHT
UACU5886331	BENT	RIGHT
UACU5886331	DENT	LEFT
UACU5886331	DENT	CORNERPOST
MRKU2574676	DENT	RIGHT
MRKU2574676	BENT	RIGHT
MRKU2574676	BENT	LEFT
MRKU2574676	DENT	FRONT
MRKU2574676	BENT	FRONT
GCXU5796378	DENT	CORNERPOST
MSKU6696674	BENT	RIGHT
MSKU6696674	DENT	BOTTOM
MSKU6696674	DENT	LEFT
FFAU5581174	DENT	RIGHT
MNBU4281430	DIRTY	BACK
CAAU5475780	DENT	LEFT
CAAU5475780	DENT	RIGHT



Without any liability accepted
Constanta South Container Terminal
Planning Department

Accepted for
repair only
without any further
action

Container	Damage type	Damage location
CAAU5475780	DENT	FRONT
HLXU8309718	DENT	CORNERPOST
HLXU8309718	BENT	FRONT
GESU1255510	DENT	DOORSYSTEM
GESU1255510	BENT	LEFT
GESU1255510	DENT	FRONT
MRKU4438935	IMO LABEL	FRONT
MRKU4438935	IMO LABEL	RIGHT
MRKU4438935	IMO LABEL	BACK
MRKU4438935	IMO LABEL	LEFT
MRKU0761282	DENT	RIGHT
MRKU0761282	BENT	LEFT
FANU1980755	DENT	RIGHT
FANU1980755	BENT	LEFT
SUDU8583259	BENT	RIGHT
SUDU8583259	BENT	LEFT
MRKU2329853	BENT	RIGHT
MRKU2329853	DENT	RIGHT
MRKU2329853	BENT	LEFT
MRSU0077673	BENT	LEFT
MRSU0077673	BENT	FRONT
MRSU0077673	DENT	FRONT
TCNU4658280	DENT	RIGHT
TCNU4658280	BENT	LEFT
UACU5475520	DENT	LEFT
FANU3383975	BENT	RIGHT
MRKU2423535	DENT	LEFT
HAMU3922709	BENT	RIGHT
CAIU9743396	DENT	LEFT
MIEU0057925	HOLE	TOPROOF
MRKU0315505	DENT	RIGHT
MRKU0315505	BENT	LEFT
MRKU0315505	DENT	CORNERPOST
CAXU5796018	BROKEN	RIGHT

Without any liability accepted
Consant's South Container Terminal
Planning Department

ACKNOWLEDGED
RECEIVED
WITHOUT ANY PREJUDICE

Container	Damage type	Damage location
CAXU5796018	DENT	RIGHT
MRSU7875058	BENT	CORNERPOST
STJU2017697	DENT	LEFT
UACU5759569	DENT	RIGHT
UACU5759569	DENT	LEFT
TXGU7117635	DENT	RIGHT
TGCU2110937	DENT	RIGHT
SUDU6808504	BENT	FRONT
SUDU6808504	BENT	RIGHT
SUDU6808504	DENT	RIGHT
SUDU6808504	BENT	LEFT
HASU4961430	BENT	RIGHT
HASU4961430	DENT	FRONT
HASU4961430	DENT	LEFT
CAAU6417900	DENT	LEFT
CAAU6417900	DENT	CORNERPOST
HLBU8306516	CUT	TARPAULIN
HLBU8306516	DENT	RIGHT
TCNU5058510	IMO LABEL	FRONT
MSKU9775798	DENT	CORNERPOST
MRKU7286693	BENT	FRONT
MRKU7286693	BENT	RIGHT
MRKU7286693	BENT	LEFT
TRHU2307510	DENT	LEFT
TRHU2307510	BENT	RIGHT
GESU6411024	DENT	RIGHT
GESU6411024	DENT	CORNERPOST
TLLU5213983	BENT	RIGHT
TLLU5213983	DENT	RIGHT
TLLU5213983	DENT	LEFT
TLLU5213983	DENT	FRONT
FANU1192774	BENT	LEFT
FCIU4218080	DENT	RIGHT
FCIU4218080	DENT	LEFT

Without any liability accepted
 Consistent South Container Terminal
 Planning Department



Signature

Container	Damage type	Damage location
HAMU4344713	BENT	FRONT
UETU5205160	DENT	RIGHT
UETU5205160	DENT	LEFT
TCNU3250185	BENT	FRONT
SUDU8841332	BENT	RIGHT
SUDU8841332	BENT	LEFT
SUDU1327126	BENT	RIGHT
SUDU1327126	DENT	CORNERPOST
HAMU3873796	DENT	DOORSYSTEM
MSKU9932080	DENT	RIGHT
MSKU9932080	BENT	LEFT
HAMU3011560	SCRATCHED	RIGHT
UACU6007083	DENT	RIGHT
TGHU9192236	BENT	FRONT
MRKU0531783	DENT	LEFT
TGBU5746791	BENT	RIGHT
MRKU7912267	DENT	LEFT
MSKU8988000	DENT	CORNERPOST
MRSU5974637	BENT	LEFT
MRSU5997041	BENT	RIGHT
MRSU5997041	BENT	LEFT
TGHU6157231	DENT	CORNERPOST
HAMU1289037	BENT	RIGHT
HAMU1289037	BENT	LEFT
MRKU4674289	DENT	LEFT
NIDU5231111	CUT	RIGHT
MSKU9753187	DENT	LEFT
HLXU8415772	BENT	CORNERPOST
HLBU2661452	DENT	RIGHT
HLBU2661452	DENT	LEFT
TCKU6003707	DENT	LEFT
HASU4034279	BENT	FRONT
HASU4034279	DENT	RIGHT
HASU4034279	BENT	LEFT



Without any liability accepted
Constant South Container Terminal
Planning Department

Acknowledged for receipt
[Signature]

Container	Damage type	Damage location
CAAU6096518	DENT	LEFT
FANU1276577	DENT	CORNERPOST
MRKU5168731	DENT	LEFT
MRKU5168731	RUSTED	FRONT
MRKU5168731	RUSTED	BACK
MRKU5168731	DENT	RIGHT
HLBU3631241	IMO LABEL	FRONT
BEAU4187556	DENT	FRONT
MSKU1531630	BENT	LEFT
TCNU1885459	DENT	LEFT
BEAU2373470	BENT	LEFT
HAMU2713900	BENT	RIGHT
TLLU8091087	DENT	RIGHT
HASU4553778	BENT	RIGHT
HASU4553778	DENT	LEFT
HASU4553778	DENT	FRONT
MRKU0327928	BENT	RIGHT
TCNU4572313	DENT	RIGHT
TCNU4572313	BENT	LEFT
UETU2199104	DIRTY	RIGHT
UETU2199104	DIRTY	BACK
UACU5562754	DENT	RIGHT
UACU5562754	DENT	LEFT
PONU2049582	DENT	LEFT
HAMU1216180	DENT	LEFT
HAMU1216180	BENT	RIGHT
HAMU1216180	DENT	RIGHT
HLBU1961938	DENT	RIGHT
MSKU1038840	DENT	RIGHT
MSKU1038840	IMO LABEL	FRONT
MSKU5941144	BENT	RIGHT
NIDU2322096	BENT	LEFT
NIDU2322096	DENT	RIGHT
MRKU8928252	DENT	FRONT

Without any liability accepted
Constant South Container Terminal
Planning Department



Container	Damage type	Damage location
MRKU8928252	BENT	RIGHT
MRKU8928252	BENT	LEFT
TRDU1892652	HOLE	TOPROOF
MRKU9701237	DENT	RIGHT
MRKU3385770	BENT	RIGHT
MRKU9491573	DENT	DOORSYSTEM
MSKU1319744	RUSTED	FRONT
MSKU1319744	DENT	RIGHT
GCXU5972857	DENT	RIGHT
HLBU1326260	DENT	RIGHT
HLBU1326260	DENT	LEFT
HLBU1326260	DENT	CORNERPOST
MRKU2294422	BENT	FRONT
MRKU2294422	BENT	RIGHT
MRKU2294422	DENT	LEFT
MRKU2294422	BENT	LEFT
FSCU7148278	BENT	FRONT
FSCU7148278	DENT	RIGHT
FANU3740692	BENT	LEFT
GCXU5138783	DENT	LEFT
HLBU1173330	BENT	RIGHT
HLBU1173330	DENT	RIGHT
HLBU1173330	BENT	LEFT
HLBU1173330	RUSTED	FRONT
TRHU4754688	BENT	LEFT
MRSU5893005	BENT	LEFT
TCKU7031447	BENT	RIGHT
TCLU3138563	BENT	FRONT
TCLU3138563	BENT	RIGHT
TCLU3138563	BENT	BOTTOM
TCLU3138563	DENT	LEFT
HLXU1229816	BENT	FRONT
MRKU0110830	BENT	LEFT
MRSU5715831	BENT	LEFT

Without any liability accepted
Constant - South Container Terminal
Planning Department

And it is accepted for
signature
without any prejudice

Container	Damage type	Damage location
TGHU6964697	DENT	CORNERPOST
TGHU6964697	BENT	FRONT
MRKU3819428	DENT	RIGHT
MRKU5072389	RUSTED	FRONT
MRKU5072389	RUSTED	BACK
MRKU5072389	BENT	RIGHT
MRKU5072389	BENT	LEFT
FANU1440839	DENT	LEFT
MRKU6292520	BENT	RIGHT
MRKU6292520	BENT	LEFT
FANU1836202	DENT	RIGHT
FANU1836202	BENT	LEFT
HAMU1312461	DENT	RIGHT
HLBU2893632	BENT	RIGHT
TIIU2002711	BENT	RIGHT
TCKU7073078	DENT	RIGHT
MSKU7685397	BENT	RIGHT
MSKU7685397	BENT	LEFT
MRKU5270316	DENT	RIGHT
HLXU8089212	BENT	RIGHT
HLXU8089212	BENT	LEFT
HLXU8089212	DENT	CORNERPOST
MAEU4217814	CUT	TARPAULIN
TGHU9711120	BENT	RIGHT
TGHU9711120	DENT	RIGHT
TGHU9711120	BENT	LEFT
TGHU9711120	DENT	LEFT
MRKU4983631	BENT	RIGHT
FANU1939643	DENT	RIGHT
TGBU6011630	IMO LABEL	RIGHT
TGBU6011630	IMO LABEL	LEFT
TGBU6011630	IMO LABEL	FRONT
TGBU6011630	IMO LABEL	BACK
CAAU6574448	DENT	CORNERPOST

Without any liability accepted
Constantly in the Container Terminal
Planning Department

Accepted for the
reception of
without any prejudice



Handwritten signature or initials.

Container	Damage type	Damage location
UACU8539315	DENT	RIGHT
MSKU3827240	BENT	LEFT
MSKU3827240	BENT	RIGHT
GESU3869266	DENT	RIGHT
MSKU9667812	DENT	RIGHT
TCLU2023718	BENT	FRONT
TCLU2023718	BENT	RIGHT
TCLU2023718	BENT	LEFT
MRSU3117770	DENT	RIGHT
GCXU6198175	CUT	FRONT
SEGU5716419	DENT	CORNERPOST
FANU1468184	DENT	RIGHT
FANU3063210	DENT	LEFT
TCNU5486689	DENT	LEFT
HASU4446532	BENT	TOPROOF
MRSU3741240	CUT	RIGHT
BMOU2668496	DENT	FRONT
BMOU2668496	DENT	LEFT
GATU8445096	DENT	LEFT
GATU8445096	RUSTED	LEFT
GATU8445096	DENT	RIGHT
GATU8445096	BENT	RIGHT
GATU8445096	DENT	CORNERPOST
GATU8445096	RUSTED	RIGHT
GATU8445096	RUSTED	BACK
MSKU3886731	BENT	FRONT
MSKU3886731	BENT	RIGHT
MRSU5299483	BENT	RIGHT
MRSU5299483	BENT	LEFT
FFAU4791453	DENT	CORNERPOST
TCNU7077524	DENT	RIGHT
TCNU7077524	BENT	RIGHT
HLBU2522143	DENT	RIGHT
HLBU2522143	BENT	LEFT

Without any liability accepted
Constant : South Container terminal
Planning Department

Acknowledged for receipt only
without any prejudice



Container	Damage type	Damage location
MRSU4002266	BENT	LEFT
MRSU4002266	DENT	LEFT
MRSU3457091	DENT	RIGHT
MRSU3457091	CUT	CORNER
SUDU1775120	BENT	LEFT
SUDU1775120	DENT	DOORSYSTEM
SUDU1775120	DENT	CORNERPOST
HAMU4269625	HOLE	TOPROOF
MRKU5446719	BENT	RIGHT
MRKU5446719	BENT	LEFT
MRSU6175717	BULGED	FRONT
MRSU6175717	BULGED	RIGHT
TRHU4945555	DENT	RIGHT
TRHU4945555	BENT	LEFT
BMOU2673682	DENT	RIGHT
MSKU0273280	BENT	FRONT
MSKU0273280	BENT	RIGHT
MSKU0273280	DENT	RIGHT
MSKU0273280	DENT	LEFT
TCKU7726927	BENT	RIGHT
TCKU7726927	DENT	RIGHT
TCKU7726927	BENT	LEFT
HLBU3153137	DENT	RIGHT
HLBU3153137	BENT	LEFT
MRKU6082951	BENT	RIGHT
MRKU6082951	DENT	LEFT
HAMU2294038	HOLE	TOPROOF
MRKU6074196	RUSTED	FRONT
MRKU6074196	DENT	RIGHT
MRKU6074196	RUSTED	BACK
MRKU6074196	BENT	LEFT
MRKU6074196	DENT	CORNERPOST
CAAU5380371	BULGED	RIGHT
HAMU3999655	BENT	LEFT



Without any liability accepted
 Constant South Container Terminal
 Planning Department

Accepted for
 loading and
 without any pre-

Container	Damage type	Damage location
FANU1723314	DENT	CORNERPOST
FANU1723314	BENT	LEFT
UACU4025447	DENT	CORNERPOST
BEAU4935072	BENT	RIGHT
SUDU7332460	DENT	CORNERPOST
SUDU7332460	DENT	RIGHT
TEMU5802658	BENT	LEFT
XINU1648555	BENT	LEFT
XINU1648555	BENT	RIGHT
MRSU7421667	IMO LABEL	RIGHT
UACU5659092	DENT	FLOOR
UACU5659092	DENT	FRONT
UACU5659092	BENT	RIGHT
BEAU6375070	DENT	LEFT
BEAU6375070	BENT	LEFT
FANU3361277	DENT	CORNERPOST
MIEU2020864	BENT	DOORSYSTEM
BMOU6663018	DENT	RIGHT
BMOU6663018	BENT	LEFT
HLXU1285358	DIRTY	LEFT
HLXU1285358	DIRTY	RIGHT
TGHU1763730	DENT	FRONT
TGHU1763730	BENT	BOTTOM
TGHU1763730	BENT	LEFT
MRKU6967352	BENT	RIGHT
MRKU0925196	DENT	RIGHT
MRKU0925196	DENT	LEFT
MSKU1253478	DENT	LEFT
MSKU1878568	BULGED	LEFT
HASU4430860	DENT	FRONT
HASU4430860	DENT	RIGHT
HASU4430860	DENT	LEFT
MRKU5013426	DENT	CORNERPOST
TEMU6159715	DENT	LEFT

Without any liability accepted
Constant South Container Terminal
Handling Department



[Handwritten signature]

Container	Damage type	Damage location
TLLU2933505	BENT	RIGHT
TLLU2933505	BENT	LEFT
TEMU6720636	DENT	RIGHT
TEMU6720636	BENT	LEFT
BEAU4717830	DENT	LEFT
TCLU9141116	IMO LABEL	RIGHT
TCLU9141116	IMO LABEL	LEFT
TCLU9141116	IMO LABEL	BACK
TCLU9141116	IMO LABEL	FRONT
MRSU4566630	DENT	FRONT
MRSU4566630	DENT	LEFT
CAIU8731153	IMO LABEL	FRONT
CAIU8731153	IMO LABEL	BACK
CAIU8731153	IMO LABEL	LEFT
CAIU8731153	IMO LABEL	RIGHT
MRKU9738787	DENT	FRONT
HLXU6685104	CUT	TARPAULIN
FFAU5222744	DENT	LEFT
UETU2838144	DENT	RIGHT
TCKU6627792	BENT	RIGHT
MNBU9166341	CUT	RIGHT
MNBU9166341	DENT	CORNERPOST
TGBU2228058	DENT	RIGHT
FANU1379220	BENT	FRONT
MSKU7754498	DENT	LEFT
MSKU7754498	DENT	CORNERPOST
SEGU2073216	DENT	LEFT
HASU4128017	DENT	RIGHT
HASU4128017	DENT	LEFT
MIEU0013629	DENT	RIGHT
MIEU0013629	DENT	LEFT
MIEU0013629	BENT	LEFT
CAAU6605852	DENT	RIGHT
CAAU6605852	DENT	LEFT

Without any fee accepted
Assistant South Container Terminal
Planning Department

Accepted by
request of
without any
signature

Container	Damage type	Damage location
MRKU0108869	BENT	RIGHT
MRKU0108869	BENT	LEFT
MRKU0108869	BENT	FRONT
TCKU7451080	IMO LABEL	FRONT
TCKU7451080	IMO LABEL	RIGHT
TCKU7451080	IMO LABEL	LEFT
TCKU7451080	IMO LABEL	BACK
SEKU6402675	DENT	LEFT
GESU6408838	DENT	RIGHT
GESU6408838	DENT	LEFT
GCXU5535121	DENT	RIGHT
MRKU7552978	BENT	RIGHT
MRKU7552978	DENT	LEFT
HASU1304107	BENT	BOTTOM
HASU1225097	BENT	RIGHT
CAAU9318516	IMO LABEL	FRONT
FANU3625322	BENT	LEFT
MSKU5130091	RUSTED	LEFT
MSKU5130091	BENT	FRONT
MSKU5130091	BENT	RIGHT
MSKU5130091	BENT	LEFT
MSKU5130091	RUSTED	FRONT
MSKU5130091	RUSTED	RIGHT
MRKU0387763	DENT	RIGHT
MRKU0387763	DENT	LEFT
FANU3195577	BENT	RIGHT
FANU3195577	DENT	FRONT
FANU3195577	BENT	LEFT
MSKU8402104	IMO LABEL	RIGHT
TRHU4575656	DENT	FRONT
TRHU4575656	DENT	LEFT
UACU5823837	BENT	RIGHT
UACU5823837	BENT	LEFT
UACU5823837	BENT	FRONT



Container	Damage type	Damage location
HLBU8102723	DENT	RIGHT
HLBU8102723	CUT	TARPAULIN
TCNU1805155	DENT	FRONT
TCNU1805155	BENT	LEFT
HAMU3447722	DENT	FRONT
HAMU3447722	BENT	DOORSYSTEM
HAMU3447722	CUT	BACK
BEAU4626350	DENT	RIGHT
BEAU4626350	BENT	RIGHT
BEAU4626350	DENT	LEFT
BEAU4626350	BENT	LEFT
HLBU8100870	CUT	TARPAULIN
HLBU8100870	DENT	CORNERPOST
MRKU5293100	BENT	LEFT
MRKU5293100	BENT	FRONT
UACU5837980	BENT	RIGHT
MRKU6318728	RUSTED	FRONT
FCIU4195786	DENT	RIGHT
TLLU5320127	DENT	CORNERPOST
FBIU0431541	DENT	RIGHT
TLLU5238322	DENT	RIGHT
TLLU5238322	DENT	LEFT
FTAU1561006	DENT	RIGHT
FTAU1561006	DENT	LEFT
HLXU1160833	BENT	FRONT
HLXU1160833	DENT	LEFT
UACU3969102	DENT	LEFT
UACU3969102	DENT	CORNERPOST
MRKU5662045	DENT	RIGHT
MRKU5662045	DENT	LEFT
MRKU5662045	BENT	LEFT
BSIU9846511	BENT	RIGHT
BSIU9846511	BENT	LEFT
MSKU5752840	DENT	FRONT

Without any liability accepted
 On island South Container Terminal
 Planning Department



A handwritten signature in black ink, appearing to be "JD".

Container	Damage type	Damage location
MRKU8197939	BENT	FRONT
MRKU8197939	BENT	RIGHT
MRKU8197939	DENT	LEFT
TGBU5913688	DENT	CORNERPOST
MRKU0945042	DENT	LEFT
MRKU5554694	BENT	RIGHT
MRKU0759768	DENT	RIGHT
MRKU0759768	DENT	LEFT

Without any liability accepted
Constantia South Container Terminal
Planning Department



Accepted
Report only
without any penalties.